## KING COUPTY INTERNATIONAL AIRPORT INCITENT REPORT

,,,,,,	KING COO T INTERNATIONAL AIR ON INC.		
INCIDENT: Fuel Spill	DATE OCCURRED 05-27-92 TIME OCCURRED 2130	DATE REPORTED	
·	TIME OCCURRED	TIME REPORTED	
LOCATION(S) OF OCCURRENCE:			
North Fuel Farm			
REPORTED BY:	PHONE NO(5):		
Galvins			
SUMMARY:			
involved. Upon arrival, S and that flow was stopped third shift was able to r at approx. 2150 to reliev who said that he was fill but neglected to disconne nozzle on the farm and sp personnel responded and m drum at their business what 2210.	LEB  LEB  LEB  LEB  LEB  LEB  LEB  LEB	gal. of Jet A was spilled D l for fire watch until esponded in FD 2 and arrived Thomas Valko, Galvins lineman, e truck and the supply line aging the single point line. Additional Galvin ds and placed them in a 55 gal Officers departed the scene	